

1	1LR	1LX
2	1LX	1RR
3	2LR	2SW
4	2LX	2RR
5	3LR	3SW
6	3LX	3RR
7	4LR	4SW
8	4LX	4RR
9		
10		

LINE RELAYS 1

1	5LR	5SW
2	5LX	5RR
3	6LR	6SW
4	6LX	6RR
5	7LR	7SW
6	7LX	7RR
7	8LR	8SW
8	8LX	8RR
9		
10		

LINE RELAYS 2

1	MA	TR1
2	MB	TR1
3	RT	L1
4	TX	L1
5	RF	
6	RR	VB
7	SCA	
8		
9	OSC	OSC
10	OSC	OSC

RINGER

1	TR1	C1 C2
2	Resistor	
3	SA	D
4	B	PR
5	MK	SP
6	KX	JG
7		ON
8	DU	
9		
10		

ALTON SPT 1 - O/G

1	SA	F
2	SB	SM
3	DF	LZ
4	RA	
5	RB	RX
6	PF	SU1
7	PS	SU1
8	PR	SU2
9	TR1	SU2
10	SCA	

COMMON EQUIPMENT

1	TR1	AC
2	SU1	TC
3	SU1	ST
4	SCA	resistor
5	OSC	OSC
6	OSC	OSC
7	MX	
8		
9		
10	MTR1	MTR2

OSAN

1	resistor	SCA
2	1AL	AP
3	2AL	AX
4	3AL	AZ
5	4AL	RA
6	5AL	FA
7	6AL	MF
8	DF	XR
9	RX	
10	relay	
11	SU1	SCB
12	SU1	SCC

EXCHANGE ALARMS

1	TR1	C1 C2
2	Resistor	
3	A	SA
4	B	CD
5	BA	SM
6	SW	AN
7	ON	
8		
9	DU	
10		

ALTON SPT 2 - I/C

1	SCA
2	
3	MF
4	PB
5	DF
6	FA

SIGNAL BOX MISC CCTS 1

1	LR
2	CB
3	RR
4	TR1
5	SCA
6	resistor

CODE PHONE

1	ANX
2	ANZ
3	
4	
5	
6	

SIGNAL BOX MISC CCTS 2

1	AL
2	AC
3	AD
4	BC
5	SU1
6	SU1
7	SCA
8	relay

BUTTS TREADLE

Medstead relay sets

Jan 2009

OSAN and BUTTS TREADLE
out of service